Oil Field Environmental Incident Summary

Responsible Party: SM Energy Company **Well Operator:** SM ENERGY COMPANY

Well Name: ISZLEY-USA 1

Field Name: CARTWRIGHT Well File #: 12216

Date Incident:1/1/2014Time Incident:13:00Facility ID Number:County:MCKENZIETwp:150Rng:104Sec:1Qtr:

Location Description:

Submitted By: Luke Studer Received By:

Contact Person: Luke Studer

PO BOX 7168

BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 180 Feet **Distance Nearest Water Well:** 180 Feet

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	0	barrels	0	barrels			
Brine	2	barrels	2	barrels	2	barrels	
Other	0	barrels	0	barrels			

Description of Other Released Contaminant:

Inspected: Written Report Received: 7/30/2014 Clean Up Concluded: 1/15/2014

Risk Evaluation:

None

Areal Extent:

N/A

Page 1 of 2

Potential Environmental Impacts:

None

Action Taken or Planned:

Shut down unit and closed flowline and drained treater to an empty oil tank. Called Tom Hedegaard and lined up a vac truck to clean up the water on the ground and recovered water and contaminated soil will be hauled to an approved disposal.

Wastes Disposal Location: Recovered water and contaminated soil to be hauled to an approved disposal.

Agencies Involved:

Updates

Date: 1/3/2014 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the spill report, this incident occurred more than two years ago. However, a call has been made to clarify details on the reporting end of the incident. This spill remained on location, according to the incident summary. NDIC retains oversight.

Date: 1/6/2014 Status: Correspondence Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

This incident occurred on January 1, 2014, according to the company man.